

### Damaged Pit List - last updated 5/4/2023

No.	Address/Location of Work	Suburb	Ward	Description of work	Received Date	Priority	Status
1	Opposite to 16 Karingal Av	Carlingford	Epping	Replaced damaged lintel by 1.8m(clear opening ) lintel with class D bike safe grate	24/06/2019	Medium	Under Investigation
2	Cressfield Av No.2	Carlingford	Epping	Replaced damaged lintel by 1.8m(clear opening ) lintel with class D bike safe grate	24/06/2019	Medium	Under Investigation
3	Mulyan Av No.2	Carlingford	Epping	Replaced damaged access lid by class D lid in front of 2 Mulyan Av, Carlingford	12/03/2019	Subject to Development	Under Investigation
4	Bardia Rd No.21	Carlingford	Epping	Replace damaged lintel by 1.8m (clear opening )lintel plus bike safe grate and standard chamber	18/02/2020	Medium	Under Investigation
5	Woodstock Rd No.10a	Carlingford	Epping	Replace damaged lid and old lintel by 2.4m lintel plus class D grate and standard pit chamber.	26/02/2020	Medium	Under Investigation
6	Fleming St No.10	Carlingford	Epping	Replace damaged pit by 1.8m (clear opening) lintel with class D bike safe grate pit chamber.	16/01/2020	Medium	Under Investigation
7	Talinga St No.7	Carlingford	Epping	Replace damaged lintel by 1.8m (clear opening) lintel plus class D grate.	27/07/2020	Medium	Under Investigation
8	Tudor PI No.4	Carlingford	Epping	Replace damaged lintel by 1.2m (clear opening) lintel plus class D bike safe grate	7/10/2020	Low	Under Investigation
9	Kay St No.21	Carlingford	Epping	Replace damaged lintel by 1.8m (clear opening) lintel plus class D bike safe grate	21/08/2020	Low	Under Investigation
10	Oakes Rd No.112	Carlingford	Epping	Replace damaged lintel by 0.9m (clear opening) lintel plus class D bike safe grate	11/03/2021	High	Under Investigation
11	Dunrossil Av No.54	Carlingford	Epping	Replace damaged lid by class D 1mx1m gatic lid	22/03/2021	Medium	Under Investigation
12	Billyard Place No.2	Carlingford	Epping	Replace damaged lintel by 1.8m (clear opening) lintel plus and D bike safe grate	15/07/2021	High	Under Investigation
13	Lachlan Grove No.7	Carlingford	Epping	Replace damaged pit by 1.8m lintel plus grate and chamber	15/07/2021	High	Capital Project
14	Balaka Dr No.138	Carlingford	Epping	Replace damaged grate by class D bike safe grate	8/09/2021	Low	Under Investigation
15	Tracey Av No.3	Carlingford	Epping	The damaged pit needs to be replaced by 2.4m lintel with class D bike safe grate.	28/09/2021	Low	Under Investigation
16	Montgomery Rd No.2	Carlingford	Epping	Replace damaged lintel by 1.8m lintel plus class D grate	12/05/2021	Subject to Development	Under Investigation
17	Ainslie Pde No.8	Carlingford	Epping	Replace damaged lintel by 2.4m lintel plus class D bike safe grate	9/04/2022	Low	Under Investigation
18	Kings Place No.1	Carlingford	Epping	Replace damaged lintel by 2.4m lintel plus class D bike safe grate with standard chamber	8/12/2021	Low	Under Investigation
19	Wyburn Av No.11	Carlingford	Epping	Replace damaged lintel by 3m lintel plus class D bike safe grate	4/08/2022	Low	Under Investigation
20	Mulyan Av No.12	Carlingford	Epping	Replace damaged pit slab	8/08/2022	Low	Under Investigation
21	Farnell Av No.52	Carlingford	Epping	Replace damaged lintel by 2.4m lintel plus class D bike safe grate as per DS24	22/10/2022	Low	Under Investigation
22	Morton Av	Carlingford	Epping	Replace damaged lintel by 1.8m lintel plus class D bike safe grate	22/10/2022	Low	Under Investigation
23	Blaxland Rd No.620	Eastwood	Epping	Replace damaged lids by class D lids	17/02/2021	High	Under Investigation
24	Terry Rd No.21	Eastwood	Epping	The damaged pit needs to be replaced by 2.4m lintel with class D bike safe grate.	17/06/2021	High	Under Investigation
25	Audine Av No.9	Epping	Epping	Replaced damaged lintel by 4.2m (clear opening) lintel plus class D grate	2/12/2018	Low	Under Investigation
26	Oxford St No.72	Epping	Epping	Replace damaged lintel by 1.8m (clear opening) lintel plus class D grate.	10/06/2020	High	Under Investigation
27	Haywood St No.24	Epping	Epping	Replace damaged lintel by 1.8m (clear opening) lintel plus class D bike safe grate	2/12/2020	Low	Under Investigation
28	Damon Av no.1	Epping	Epping	Replace damaged lintel by 3.6m (clear opening) lintel with class D bike safe grate with standard chamber	20/05/2021	Subject to Development	Under Investigation
29	Oxford St No.34-36	Epping	Epping	Replace damaged butterfly grates by class D gatic grates	23/08/2021	Low	Under Investigation
30	Dunlop St No.2	Epping	Epping	Replace damaged lintel by 1.8m lintel plus class D bike safe grate	27/07/2021	Low	Under Investigation
31	Treeview Place No.3	Epping	Epping	Replace damaged lintel by 1.8m lintel plus class D bike safe grate at 3 Treeview Place	1/04/2022	Low	Under Investigation
32	Delaward St No.22	Epping	Epping	Replace damaged lintel by 1.8m lintel plus class D bike safe grate with standard chamber	11/04/2022	High	Under Investigation
33	Patya Close No.4	Epping	Epping	Replace damaged lintel by 1.2m lintel ( Clear opening) plus class D bike safe grate as per DS21	21/07/2022	Low	Under Investigation
34	Boronia Av No.34	Epping	Epping	Replace damaged lid	20/12/2022	Low	Under Investigation
35	Ray Rd No.107	Epping	Epping	Replace damaged lintel by 1.8m lintel plus class D bike safe grate as per DS21	20/12/2022	Subject to Development	Under Investigation
36	Haywood St No.5	Epping	Epping	Replace damaged lintel by 2.4m lintel ( Clear opening) plus class D bike safe grate with pit chamber as per DS24	22/09/2022	Low	Under Investigation
37	Becky Av No.39	North Rocks	Epping	Replace damaged lintel by 1.8m (clear opening) lintel with class D bike safe grate.	20/05/2021	Subject to Development	Under Investigation
38	Williams Rd No.14	Nth Rocks	Epping	Replace damaged grate by class D bike safe grate	8/03/2022	Low	Under Investigation
39	Lamorna Av No.92	Beecroft	Epping	Replace damaged lintel by 1.8m (clear opening) lintel plus class D grate.	6/05/2020	Subject to Development	Under Investigation
40	Karril Av No.15	Beecroft	Epping	Replace damaged lid by raised letterbox pit grate	11/10/2021	Low	Under Investigation
41	Jenkins Rd No.21-25	Carlingford	North Rocks	Replace damaged lintel by 3m lintel ( Clear opening) plus class D bike safe grate as per DS24	20/04/2022	High	Under Investigation
42	Rivera Av No.8	North Rocks	North Rocks	Replace damaged lintel by 1.8m (clear opening) lintel with class D bike safe grate with standard chamber	3/03/2021	Low	Under Investigation
43	Plymouth Av No.2	North Rocks	North Rocks	The damaged pit needs to be replaced by 1.8m lintel with chamber plus class D grate.	15/04/2021	Low	Under Investigation
44	Nth Rocks Rd No.252	Nth Rocks	North Rocks	Replace damaged lintel by 1.8m lintel plus class D bike safe grate	22/10/2022	High	Under Investigation
45	Lawndale Av No.43	Nth Rocks	North Rocks	Replace damaged lintel by 1.8m lintel plus class D bike safe grate	30/01/2023	Medium	Under Investigation
46	Panora Av No.3	Nth Rocks	North Rocks	Replace damaged concrete lid by 900x900 lid	13/01/2023	High	Under Investigation
47	Huxley Drive No.6	Winston Hills	North Rocks	Replaced damaged lintel by 1.8m(clear opening ) lintel with class D bike safe grate.	11/02/2020	Medium	Under Investigation
48	Twain St No.23	Winston Hills	North Rocks	Replaced damaged lintel by 1.8m(clear opening ) lintel plus class D bike safe grate.	22/02/2020	Subject to Development	Under Investigation
49	Junction Rd No.196	Winston Hills	North Rocks	Replace damaged lintel by 2.4m (clear opening) lintel plus class D grate.	4/06/2020	High	Under Investigation
50	Gibbon Rd No.82	Winston Hills	North Rocks	Replace damaged lintel by 3m (clear opening) lintel plus class D bike safe grate	7/10/2020	High	Under Investigation
51	Weemala St No.27	Winston Hills	North Rocks	Replace damaged lintel by 1.2m (clear opening) lintel plus class D bike safe grate	18/03/2021	Low	Under Investigation
52	Selkirk St No.25	Winston Hills	North Rocks	The damaged pit needs to be modified by 1.8m lintel with chamber plus class D grate.	10/02/2021	Medium	Under Investigation
53	Weemala St No.2	Winston Hills	North Rocks	The damaged pit needs to be replaced by 1.8m lintel with class D bike safe grate.	13/10/2021	Medium	Under Investigation
54	Caroline Chisholm Dr No.131	Winston Hills	North Rocks	The damaged pit needs to be replaced by 1.8m lintel with class D bike safe grate.	1/11/2021	Low	Under Investigation
55	Dodson Cr No.20	Winston Hills	North Rocks	Replace damaged lintel by 2.4m lintel plus class D bike safe grate	20/04/2022	Low	Under Investigation
56	Glgin Place No.15	Winston Hills	North Rocks	Replace damaged lintel by 1.8m lintel plus class D bike safe grate with standard chamber	1/09/2022	Low	Under Investigation
57	Braddock Place No.7	Baulkham Hills	North Rocks	Replace damaged lintel by 2.4m (clear opening) lintel plus class D grate.	10/06/2020	Low	Under Investigation
58	Greenleaf St No.6	Constitution Hills	Parramatta	Replaced damaged lintel by 1.8m(clear opening ) lintel with class D bike safe grate plus standard pit chamber	22/03/2019	Low	Under Investigation
59	Bulli Rd No.137	Constitution Hills	Parramatta	Replace lintel by 1.8m(clear opening)lintel plus class D bike safe grate with standard chamber	23/09/2019	High	Under Investigation

No.	Address/Location of Work	Suburb	Ward	Description of work	Received Date	Priority	Status
60	Apple St No.6	Constitution Hills	Parramatta	Replace damaged pit by 1.8m lintel plus class D grate and chamber with 2m K & G	19/03/2019	Medium	Under Investigation
61	Greenleaf St No.20	Constitution Hills	Parramatta	Replace damaged lintel by 1.8m lintel plus class D bike safe grate with pit chamber	8/08/2022	Subject to Development	Under Investigation
62	Greenleaf Street No.21	Constitution Hills	Parramatta	Replace damaged lintel by 1.8m lintel plus class D bike safe grate with chamber as per DS21	25/01/2023	Low	Under Investigation
63	Castle St	Nth Parramatta	Parramatta	Replace damaged grate by class D bike safe grate	15/07/2021	High	Under Investigation
64	Pennant Hills Rd No.53	Nth Parramatta	Parramatta	Replace damaged RMS pit at opposite to 53 Pennant Hills Rd	22/12/2021	High	Under Investigation
65	Castle St	Nth Parramatta	Parramatta	Replace damaged grate by class D bike safe grate	6/09/2022	High	Under Investigation
66	Macarthur St ( outside 7	Parramatta	Parramatta	Replace damaged lintel by 1.8m (clear opening) lintel plus class D grate.	21/11/2019	High	Under Investigation
67	O'Connell St No.2-6	Parramatta	Parramatta	Replace damaged lintel by 1.8m (clear opening) lintel plus class D bike safe grate	19/10/2020	High	Under Investigation
68	George St No.75	Parramatta	Parramatta	Replace damaged lintel by 1.8m (clear opening) lintel with class D bike safe grate	21/12/2020	High	Under Investigation
69	Erby Place	Parramatta	Parramatta	Replace damaged grate by class D bike safe grate	6/04/2021	High	Under Investigation
70	Victoria Rd No.6	Parramatta	Parramatta	Replace damaged lintel by 1.8m lintel plus class D grate	30/11/2021	High	Under Investigation
71	Picasso Cr No.39	Toongabbie	Parramatta	Replace damaged lintel by 1.8m (clear opening) lintel with chamber plus class D bike safe grate	21/10/2020	Subject to Development	Under Investigation
72	Chalmers Cr No.6	Toongabbie	Parramatta	Replace damaged lid by standard lid	2/06/2021	High	Under Investigation
73	Bulli Rd No.84	Toongabbie	Parramatta	Replace damaged lintel by 1.8m lintel plus class D grate with standard chamber.	3/12/2021	Subject to Development	Under Investigation
74	Potter St No.11	Toongabbie	Parramatta	Replace damaged rear pit cover by 550x1000	11/10/2021	Low	Under Investigation
75	Reynolds St No.8	Toongabbie	Parramatta	Replace damaged lintel by 1.8m lintel plus class D bike safe grate	11/04/2022	Medium	Under Investigation
76	Edison Pde No.73	Winston Hills	Parramatta	Replace damaged lintel by 2.4m lintel plus class D bike safe grate with pit chamber	8/08/2022	Low	Under Investigation
77	Wentworth St No.60	Clyde	Rosehill	Replace damaged lintel by 3m lintel plus class D bike safe grate	11/05/2022	Medium	Under Investigation
78	Swane St No.8	Ermington	Rosehill	Replace damaged lid by class D gatic lid	1/02/2019	Medium	Under Investigation
79	Jervis St No.6	Ermington	Rosehill	Replace damaged lintel by 3.0m lintel plus class D bike safe grate with standard chamber	27/07/2021	Subject to Development	Out for Quotation
80	Swane St No.13	Ermington	Rosehill	Replace damaged lintel by 1.8m lintel plus class D bike safe grate as per DS21	20/12/2022	Subject to Development	Under Investigation
81	Carter St No.34	Lidcombe	Rosehill	Replace damaged grate by class D bike safe grate	30/10/2019	High	Out for Quotation
82	Stockyard Boulevard No.10	Lidcombe	Rosehill	Replace damaged lintel by 1.8m lintel ( Clear opening) plus class D bike safe grate as per DS24	5/07/2022	Subject to Development	Out for Quotation
83	Alma St No.11	Parramatta	Rosehill	Replace damaged grate by class D bike safe grate	12/06/2019	High	Under Investigation
84	Alice St No.71	Rose Hill	Rosehill	Replace damaged lintel by 2.4m (clear opening) lintel plus class D grate.	10/06/2020	Medium	Under Investigation
85	Devon St No.7	Rose Hill	Rosehill	Replace damaged lintel by 1.2m (clear opening) lintel plus class D bike safe grate	4/01/2021	Subject to Development	Under Investigation
86	Adeline St No.20	Rydalmere	Rosehill	Replace missing grate	19/09/2022	Low	Under Investigation
87	Carolyn St No.6	Silver water	Rosehill	Replace damaged grate by class D bike safe grate	31/01/2020	Subject to Development	Under Investigation
88	Holker St	Silver water	Rosehill	Replace damaged lintel by 1.8m (clear opening) lintel plus class D grate.	10/06/2020	High	Out for Quotation
89	Hill Rd No19-21	Wentworth Point	Rosehill	Replace damaged pit by 1.8m lintel plus class d grate with 10m K & G.	2/12/2021	High	Out for Quotation
90	Bennelong Pkway No.7	Wentworth Point	Rosehill	Replace damaged lintel by 2.4m lintel plus class D bike safe grate	7/03/2022	Medium	Out for Quotation
91	Dandarbong Ave No.56	Carlingford	Epping	Patch around pipe and provide 300mm surround to existing pit	TBC	High	Under Investigation
92	Raimonde Rd No.75	Carlingford	Epping	Replace damaged pit by 1.8m lintel plus grate and chamber	TBC	Medium	Under Investigation
93	Marsden Rd No.237	Carlingford	Epping	Replace with Class D Gatic Lid with 300mm reinforced concrete surround	TBC	High	Under Investigation
94	Marsden Rd No.228	Carlingford	Dundas	Replace damaged pit by 900mm lintel plus grate	TBC	Medium	Under Investigation
95	James St & Jenkins Rd	Carlingford	North Rocks	Replace damaged pit by 900mm lintel plus grate	TBC	High	Under Investigation
96	Yates Ave No.51	Dundas Valley	Dundas	Replace damaged pit by 1.8m lintel plus grate and extended chamber and Class D Gatic Lid at the rear	TBC	High	Out for Quotation
97	Yates Ave No.17	Dundas Valley	Dundas	Raise Buried pit to Surface	TBC	High	Out for Quotation
98	Midson Rd & Lewis St	Epping	Epping	Remove disused convertor and appox 3m of pipeline	TBC	High	Under Investigation
99	Wingrove Ave No.26	Epping	Epping	Damaged Lid from NBN works Replaced with Class D Lid and 300mm surround	TBC	Subject to Development	Under Investigation
100	Hill Rd & Carter St	Lidcombe	Rosehill	Replace damaged pit by 2.4m lintel plus grate	TBC	High	Out for Quotation
101	Hassall St No104-106	Parramatta	Rosehill	Replace damaged lintel by 1.2m lintel plus class D bike safe grate	TBC	High	Under Investigation
102	George St No.93	Parramatta	Parramatta	Replace with 900mm Lintel and extended Chamber in road appox 800mm	TBC	High	Under Investigation
103	Barrack Lane & George St	Parramatta	Parramatta	Replace with Class D 900x900 Gatic Lid	11/11/2021	High	Under Investigation
104	Bobart St	Parramatta	Rosehill	Remove concrete access cover and replace with a new 900x900 c/o Class D, 1 slab of footpath and patch up around pipe	TBC	High	Under Investigation
105	Yeramba St No.8	Rydalmere	Dundas		7/02/2023	Subject to Development	Under Investigation
106	Holker St	Silverwater	Rosehill	Custom made Grate to be installed and road plate returned to depot	TBC	High	Under Investigation
107	Hill Rd & Burroway Rd	Wentworth Point	Rosehill	butterfly Grate to be completed part of road renewal from development	TBC	High	Capital Project
108	Rebecca Pde No.51	Winston Hills	North Rocks	Replace precast lid with Class D Gatic lid Cast insitu 300mm surround	TBC	High	Under Investigation
109	Felton Rd No.83	Carlingford	Dundas	Replace damaged lintel by 1.8m lintel plus class D grate.	3/09/2021	Subject to Development	Under Investigation
110	Dorahy St No.15	Dundas	Dundas	Replace damaged lintel by 1.8m lintel with pit chamber plus class D grate.	11/06/2021	Medium	Out for Quotation
111	Park Rd No.137	Dundas	Dundas	Replace damaged grate by class D bike safe grate	3/09/2021	Medium	Out for Quotation
112	Hart St No.8	Dundas Valley	Dundas	Replace damaged lid by class D gatic lid	15/07/2021	Medium	Out for Quotation
113	Bass St No.11	Ermington	Dundas	Reconstruction of damaged old type lintel by 1.8m (clear opening )lintel with pit chamber plus class D bike safe grate.	11/10/2019	Subject to Development	Under Investigation
114	Spurway St No.123	Ermington	Dundas	Replaced damaged lintel by 1.2m (clear opening) lintel plus class D biake safe grate	1/04/2020	Medium	Under Investigation
115	Sinfield St no.8	Ermington	Dundas	Replace damaged lintel by 1.8m lintel plus class D bike safe grate with standard chamber	13/12/2021	Subject to Development	Under Investigation
116	Ashcroft St No.23	Ermington	Dundas	Replace damaged lintel by 1.8m lintel plus class D bike safe grate with standard chamber	8/08/2022	Subject to Development	Under Investigation
117	Greens Av No.45	Oatlands	Dundas	Replace damaged lintel by 3.2m (C.O) lintel plus class D grate.	11/06/2021	Medium	Under Investigation
118	Volmer St No.2	Oatlands	Dundas	Replace damaged lintel by 2.4m lintel plus class D bike safe grate with standard chamber	11/05/2022	High	Under Investigation
119	Morton St No.8	Parramatta	Dundas	Reconstruction of damaged old type lintel by 1.8m (clear opening )lintel with pit chamber plus class D bike safe grate.	18/06/2018	Subject to Development	Under Investigation
120	Pitt St No.1	Parramatta	Dundas	Replace damaged lintel by 2.4m (clear opening) lintel plus class D bike safe grate	7/10/2020	High	Under Investigation

No.	Address/Location of Work	Suburb	Ward	Description of work	Received Date	Priority	Status
121	Garden St No.5	Telopea	Dundas	Replace damaged lintel by 2.4m lintel plus class D bike safe grate	25/01/2023	Subject to Development	Under Investigation
122	Tintern Ave Cnr Felton St	Telopea	Dundas	Reconstruction of Two damaged lintels but there is a island and pram ramp issues that will need to be designed	TBC	High	Capital Project
123	Wharf Rd	Melrose Park	Rosehill	Damaged Grate requires preplacement with Class D bike Safe Grate	TBC	High	Under Investigation
124	Apollo Pl No.7	Eastwood	Epping	Replaced damaged lintel by 3.6m lintel plus grate as per D4	20/2/2023	Subject to Development	Under Investigation
125	Birnie Ave No.12	Lidcombe	Rosehill	Damaged Private Pit On Private Land	14/08/2017	High	Under Investigation
126	Birnie Ave No.12	Lidcombe	Rosehill	Damaged Private Pit On Private Land	14/08/2017	High	Under Investigation
127	Favell St No.17	Toongabbie	Parramatta	Damaged Lintel near driveway	TBC	High	Capital Project
128	Firehorse Lane	Parramatta	Rosehill	Damage Pit in the middle of laneway Aziz to check if private pit	TBC	High	Under Investigation
129	Stevens St Cnr Mitchell	Ermington	Dundas	Damaged Pit under road will require design as 40lm of K&G to be reconstructed	TBC	High	Capital Project
130	Tucks Rd No.1a	Toongabbie	Parramatta	Will require a Design on the pit as this will be a large Chamber under roadway which will require certification	TBC	High	Under Investigation
131	Cambridge Av No.15	Nth Rocks	Nth Rocks	Damaged lintel needs to be reconstructed by 1.8m lintel plus class D grate with K & G both side	23/02/2023	Medium	Under Investigation
132	Albany St No.1	Ermington	Rosehill	Damaged lintel needs to be reconstructed by 1.8m lintel plus class D grate with K & G both side	22/10/23	Medium	Under Investigation
133	Rawson St Carpark	Epping	Epping	Reconstruct new 900x900mmx600mm pit with Class D Gatic Lid with Appox 20m2 of Asphalt	24/02/2023	High	Under Investigation
134	Reynolds St Park	Toongabbie	Parramatta	Replace damaged lid	TBC	Medium	Under Investigation
135	Jervis St No.3	Ermington	Rosehill	Replace damaged lintel by 3.0m Curved lintel plus class D bike safe grate with standard chamber	27/07/2021	Subject to Development	Out for Quotation
136	Lindsay Av No.37	Ermington	Rosehill	Reconstruction of damaged lintel by 2.4m lintel plus class D grate and chamber as per DS24	14/3/2023	Medium	Under Investigation
137	Pinetree Av No.11	Carlingford	North Rocks	Reconstruction of damaged lintel by 1.8m lintel plus class D grate as per DS21	21/3/2023	Low	Under Investigation
138	Wentworth Av No.223	Toongabbie	Parramatta	Replace damaged grate by class D bike safe grate	23/3/2023	Medium	Under Investigation
139	Disraeli Rd No.8	Winston Hills	North Rocks	Reconstruction of damaged lintel plus class D grate	2/02/2023	High	Under Investigation
140	Lower Mount St No.28	Wentworthville	Parramatta	Reconstruction of the damaged lintel by 1.8m lintel plus class D grate	27/3/2023	High	Under Investigation
141	Murray Farm Rd No.25	Carlingford	North Rocks	Reconstruction of damaged pit with class D grate	4/03/2023	Low	Under Investigation